

COFC

1000 Eagle Gate Tower, 60 East South Temple | Salt Lake City, Utah 84111

(801) 533-9800 | Fax: (801) 328-1707 | www.wnlaw.com

PATENT Docket No. 15436.247.2.1.2

Art Unit

2611

AUG 1 1 2008

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re application of

Aronson et al.

Serial No.:

10/629,725

Filed:

For:

July 28, 2003

INTEGRATED CIRCUIT WITH DUAL EYE

OPENERS

Examiner:

Emmanuel Bayard

Patent No.:

7,099,382 B2

Issue Date:

Aug. 29, 2006

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1:323

Attn: Certificate of Correction Branch Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Certificate

of Correction

Sir:

In accordance with the provisions of 37 C.F.R. § 1.323 which implement 35 U.S.C. § 255, the Commissioner is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form 1050 reflects the desired corrections. Also enclosed please find a check in the amount of \$100.00 to cover the costs for issuance of this certificate.

08/12/2008 MBLANCO 00000022 7099382

01 FC:1811

160.00 OP

RECEIVED-UP Patent Publication AUG 1 3 2008

Assistant Commissioner for Patent	t
Page 2	

The Commissioner is hereby authorized to charge payment of any fees associated with this communication or credit any overpayment to Deposit Account No. 23–3178. Duplicate copies of this letter are enclosed.

Dated this 6 day of August, 2008.

Respectfully submitted,

R. Burns Israelsen Attorney for Patentee Registration No. 42,685 Customer No. 022913

RBI:ngm Docket No. 15436.247.2.1.2 Certificate of Correction Documents (with check)


CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313–1450, on this day of August, 2008.

Micholes M. Pall

Transmitted:

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323, PTO Form 1050 and Check No. 159301 for \$100.00





1000 Eagle Gate Tower, 60 East South Temple | Salt Lake City, Utah 84111 Tel: (801) 533-9800 | Fax: (801) 328-1707 | www.wnlaw.com

PATENT

Docket No. 15436.247.2.1.2

Art Unit 2611

IG 1 1 2008

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

re application of

Aronson et al.

Serial No.:

10/629,725

Filed:

July 28, 2003

For:

INTEGRATED CIRCUIT WITH DUAL EYE

OPENERS

Examiner:

Emmanuel Bayard

Patent No.:

7,099,382 B2

Issue Date:

Aug. 29, 2006

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1:323

Attn: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313–1450

Sir:

In accordance with the provisions of 37 C.F.R. § 1.323 which implement 35 U.S.C. § 255, the Commissioner is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form 1050 reflects the desired corrections. Also enclosed please find a check in the amount of \$100.00 to cover the costs for issuance of this certificate.

Assistant Commissioner for	Patents
Page 2	

The Commissioner is hereby authorized to charge payment of any fees associated with this communication or credit any overpayment to Deposit Account No. 23–3178. Duplicate copies of this letter are enclosed.

Dated this 6 day of August, 2008.

Respectfully submitted,

R. Burns Israelsen Attorney for Patentee Registration No. 42,685 Customer No. 022913

RBI:ngm Docket No. 15436.247.2.1.2 Certificate of Correction Documents (with check)


CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on this day of _______, 2008.

Wicholes M. Dall

Transmitted:

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323, PTO Form 1050 and Check No. 159301 for \$100.00



AUS 1 3 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

of 4

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006


INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 3, replace Fig. 3 with the Figure depicted herein below, wherein the label "205a" has been changed to --205b---



MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

AUG 1 3 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

Page

APPLICATION NO. : 10/629,725

ISSUE DATE.

: Aug. 29, 2006

INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 12, replace Fig. 12B with the Figure depicted herein below, wherein the second loopback has been labeled --410--




Fig. 12B

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

AUG 1 3 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006


INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 27, replace Fig. 23 with the figure depicted herein below, wherein the Data Path has been labeled -- 2800--



Column 5

Line 18, change both instances of "205" to -205b--

Line 34, change "205" to --205b--

Line 40, change "205" to --205b--

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 3 2008

Full Films floor

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

Page 4

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006

INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7

Line 2, change "945b" to -945d--

Line 7, change "945b" to -945d--

Line 11, change "945a" to -945e-

Line 20, change "network" to --host--

Line 21, change "host" to --network--

Line 56, remove [320]

Line 59, remove [320]

Line 67, change "205b" to --205a--

Column 8

Line 1, remove [320]

Line 3, remove [320]

Line 37, after "control", insert -- 389--

Line 48, change "pass-through" to -bypass--

Column 9

Line 26, change "9A" to --9-

Line 38, change "935b" to --925b--

Column 13

Line 23, change "534" to --925a--

Column 14

Line 32, before "signal", insert -- the-

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 3 2008

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

DOC Code: COCIN

: 7,099,382 B2

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006


INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 3, replace Fig. 3 with the Figure depicted herein below, wherein the label "205a" has been changed to -- 205b--



MAILING ADDRESS OF SENDER (Please do not use customer number

Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

AUG 1 3 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006


INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 12, replace Fig. 12B with the Figure depicted herein below, wherein the second loopback has been labeled --410--



MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

AUG 1 3 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

Page 3 of 4

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006


INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 27, replace Fig. 23 with the figure depicted herein below, wherein the Data Path has been labeled --2800--



Column 5

Line 18, change both instances of "205" to -205b-

Line 34, change "205" to --205b---

Line 40, change "205" to --205b--

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

AUG 1 3 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,099,382 B2

Page 4 of 4

APPLICATION NO. : 10/629,725

ISSUE DATE

: Aug. 29, 2006

INVENTOR(S)

: Aronson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7

Line 2, change "945b" to -945d--

Line 7, change "945b" to -945d--

Line 11, change "945a" to -945e--

Line 20, change "network" to --host--

Line 21, change "host" to -network-

Line 56, remove [320]

Line 59, remove [320]

Line 67, change "205b" to --205a-Column 8

Line 1, remove [320]

Line 3, remove [320]

Line 37, after "control", insert -- 389--

Line 48, change "pass-through" to -bypass--

Column 9

Line 26, change "9A" to -9-

Column 12

Line 38, change "935b" to --925b--

Column 13

Line 23, change "534" to -925a--

Column 14

Line 32, before "signal", insert --the--

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple

Salt Lake City, Utah 84111

AUG 1 3 2008